

Imagen 2 / Image 2 / Bild 2 / Immagine 2






Es posible que sean necesarios unos tornillos más largos que los originales y casquillos de suplemento.




It may be necessary screws longer than the original and extra caps.

Es kann notwendig Schrauben, die länger als die ursprünglichen und zusätzlichen Kappen sein.

Il peut être nécessaire vis plus longues que les originaux et extra bouchons.

Potrebbe essere necessario utilizzare viti più lunghe dell'originale e tappi aggiuntivi.





| ID. | DESCRIPCIÓN | DESCRIPTION | BEZEICHNUNG | QTY. |
|-----|------------------------|---------------------|----------------------------|------|
| 1 | Tornillo M6x25 ISO7380 | M6x25 ISO7380 screw | M6x25 ISO7380 Schrauben | 8 |
| 2 | Arandela M6 | M6 washer | M6 Unterlegscheibe | 8 |
| 3 | Casquillo | Spacer | Buchse | 4 |
| 4 | Silentblock | Silentblock | Silentblock | 8 |
| 5 | Arandela M6 DIN9021 | M6 DIN9021 washer | M6 DIN9021 Unterlegscheibe | 8 |
| 6 | Tuerca M6 DIN6923 | M6 DIN6923 nut | M6 DIN6923 Schraubenmutter | 8 |